

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2020-00019835					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle#1 was traveling west on Route 88 near the intersection of Van Zile Rd. Vehicle#2 was traveling in front of Vehicle#1. Driver#2 slowed down then began to make a right turn from Route 88 onto Van Zile Rd. north. Driver#1 stated that he attempted to stop, but when he applied the brakes they locked up and due to the road conditions (raining/wet) his vehicle was unable to stop. Vehicle#1 then crashed into Vehicle#2. Driver#2 stated that she was make in a right turn when she was struck by Vehicle#1. Driver#1 was determined to be at fault. Driver#2 complained of head and neck pain but refused first aid. Driver#1 refused first aid. Vehicles were moved prior to my arrival.


146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Brian D Ulman	215	Joseph L Rossi	240	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00019835

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Brian D Ulman

Officer's Signature

215

Badge Number