

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00075496			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling on Route 88 east and went through the red light at the intersection of Route 70, attempting to turn left and continue on Route 88 east. Vehicle 2 was west on Route 88, at the intersection of Route 70. Vehicle 2 proceeded into the intersection when the traffic signal turned green, making a left onto route 70 west. Vehicle 1 collided with vehicle 2 at a right angle on the passenger side, within the intersection. The impact caused vehicle 2 to flip onto it's driver's side and spin 180 degrees, coming to a stop in that position within the intersection.

Driver 1 stated he had left Home Depot and was traveling east on Route 88 and he was approaching the intersection of Route 70. Driver 1 stated he was trying to determine if he was able to make a left turn onto Route 88 to continue east as he neared the intersection. Driver 1 stated he entered the intersection to attempt to make his turn when he collided with vehicle 2 but he did not remember anything else.

Driver 2 stated she was turning left onto Route 70 west from Route 88 west and that the traffic signal was green. Driver 2 stated that vehicle 1 went through a red light from Route 88 east and collided with her vehicle within the intersection.

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2019-00075496

145 Crash Description

A witness on scene who is an off duty police officer stated he observed vehicle 2 turning left from Route 88 west onto Route 70 west through a green traffic signal. He also stated that he observed vehicle 1 traveling on Route 88 east, go through the red light at the intersection of Route 70, subsequently colliding with vehicle 2, causing the rollover. A witness statement form was completed.

Investigation revealed that the cause of the crash was due to driver 1 failing to stop at a red traffic signal.

Michael A DeFluri

Officer's Signature

270

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2019-00075496

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



Michael A DeFluri

Officer's Signature

270

Badge Number