

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00076325			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 collided with Vehicle #2 in a rear end crash at the intersection of RT 70 and Olden Street.

Driver of Vehicle #1 stated the left turn traffic light signal turned green and Vehicle #2 started traveling forward into the intersection. Driver #1 stated Vehicle #2 stopped suddenly and he was unable to apply his vehicles brakes fast enough to avoid the crash. Vehicle #1 sustained minor front end damage.

Driver of Vehicle #2 stated the left turn traffic light turned green and as he traveled forward though the intersection a Brick ambulance was passing through with lights and sirens. Driver #2 stated due to the Ambulance passing though he stopped his vehicle to let it pass. As a result Vehicle #1 collided with the rear of his vehicle. Vehicle #2 sustained minor rear end damage.

Based on my observations and statements made by both parties I found the driver of Vehicle #1 at fault for the crash for following to closely.

146. Officer's Signature Frank James Giambona	147. Badge # 290	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2019-00076325

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Olden Street

NOT TO SCALE



Highway 70

Frank James Giambona

Officer's Signature

290

Badge Number