

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00079204			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Upon arrival, both vehicles were removed from the roadway and relocated in an adjacent parking lot.

Driver #2 stated he was traveling west on Route 88 in the left lane. Driver #2 said he was the first vehicle stopped for the red traffic signal at the intersection for Route 70. Driver #2 stated while his vehicle was stopped, the front bumper of vehicle #1 struck the rear bumper to his vehicle causing a crack in the bumper along with minor scratches.

Driver #1 stated he was traveling directly behind vehicle #2 and was also stopped for the red traffic signal.

Driver #1 stated his foot slipped off the brake pedal and the vehicle began to roll forward and before he was able to re-apply the brake, the front of vehicle #1 struck the rear of vehicle #2.

Both vehicles had minor damage.

On scene investigation determined driver #1 to be at fault for driver inattention.

146. Officer's Signature Richard J Zimmerer	147. Badge # 272	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2019-00079204

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



Richard J Zimmerer

272