

[illegible]

New Jersey Police Crash Investigation Report												Case Number 2019-00070544			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 01 was traveling north on Jack Martin Blvd and had made a left turn into 425 Jack Martin Blvd when it collided with Vehicle 02 traveling south on Jack Martin Blvd.

Driver of Vehicle 01 stated she was north on Jack Martin Blvd and had made a left turn into 425 Jack Martin Blvd when she was struck in the right rear by Vehicle 02 traveling south on Jack Martin Blvd. Driver of Vehicle 01 stated she didn't see Vehicle 02 until the last second and that Vehicle 02 must have been speeding.

Driver of Vehicle 02 stated she was traveling south on Jack Martin Blvd. when suddenly Vehicle 01 made a left turn in front of her into 425 Jack Martin Blvd. causing Vehicle 02's right front to strike Vehicle 01's right rear.

146. Officer's Signature Robert Koch	147. Badge # 170	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2019-00070544

144 Crash Diagram (NOT TO SCALE)



SONNY
LN

JACK MARTIN BLVD



425
JACK MARTIN
BLVD

Robert Koch

Officer's Signature

170

Badge Number