

96	Page 1 of 4		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a									
05	1. Case Number				2019-00071853										10. Crash Occurred On: RT 88		11. Speed Limit		3 5		118b									
97	2. Police Dept. of				Code		Brick Police										01		12. Route No.		Suffix		119a							
01	3. Station/Precinct																600		14		15		16		119b					
98	4. Date of Crash				5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured		19. To: 17. Cross Road Name/Route No.		18. Speed Limit		2		5		119c							
01	mm dd yy				Su M Tu W Th F Sa		1 3 2 8		1 5 0 6		-		0 1		-		-		-		-		120a							
02	23. Veh. #				24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code		21. Latitude		20. Route Name/Route No.		22. Longitude				120b							
04	01				*		*		02		4936627653		148		-		-		-		-		120c							
101	26. Driver's First Name				Initial		Last Name		29. Sex		56. Driver's First Name		Initial		Last Name		59. Sex						121a							
02	Christopher				C		Beggs		M		Michael		A		Kluxen		M						121b							
102	27. Number & Street										57. Number & Street												122							
01	91 DOE COURT										1219 LEWIS RD												123							
103	28. City				State		Zip				58. City		State		Zip								124							
01	BRICK TOWNSHIP				NJ		08723				Point Pleasant Borough		NJ		08742								125							
104	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State		126a							
02	0 4				A		-		-		NJ		0 5		D		-		-		NJ		56							
105	32. Driver's License Number				33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires										126b							
09	B 2 2 2 2				1 2 4 6 3		0 1 7 2 4		K 5 6 7 2		5 4 4 6 1		0 2 6 4 5		0 2 0 9 6 4		0 9 2 0						126c							
106	35. Owner's First Name				Initial		Last Name		65. Owner's First Name		Initial		Last Name										126d							
—	Same as Driver				YRC INC				Same as Driver		Toyota Lease Trust												126e							
107	36. Number & Street								66. Number & Street														127a							
—	10990 ROE AVE								PO BOX 105386														26							
108	37. City				State		Zip		67. City		State		Zip										127b							
25	Overland Park				KS		66216		Atlanta		GA		30348										127c							
109	38. Make				39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		73. State		127d			
01	Volvo				—		BL		2007		2324760		IN		Toyota		Camry		GY		2018		E33JSK		NJ		127e			
110	44. VIN				45. Expires				74. VIN		75. Expires														128					
02	1 J J V 2 8 1 D 7 L L 2 1 6 5 1 8				—				4 T 1 B 1 1 H K 1 J U 5 2 3 3 2 5		01/21														129					
111	46. Vehicle Removed to:								76. Vehicle Removed to:																130					
—	☒ Driven				☐ Towed Disabled		☐ Towed Disabled & Impounded		☐ Driven		☒ Towed Disabled		☐ Towed Disabled & Impounded												131					
112	☐ Left at Scene				☐ Towed Impounded				☐ Left at Scene		☐ Towed Impounded														132					
113	47. Authority								77. Authority																133					
—	☐ Owner				☒ Driver		☐ Police		☐ Owner		☐ Driver		☒ Police												134					
114	48. Alcohol Drug Test				49. Hazardous Material				78. Alcohol Drug Test		79. Hazardous Material														135					
—	Given: ☒ No ☐ Yes ☐ Refused				Given: ☒ None ☐ On Board ☐ Spill				Given: ☒ No ☐ Yes ☐ Refused		Given: ☒ None ☐ On Board ☐ Spill														136					
115	Type: ☐ Breath ☐ Blood ☐ Urine				Type: ☐ Breath ☐ Blood ☐ Urine				Type: ☐ Breath ☐ Blood ☐ Urine		Type: ☐ Breath ☐ Blood ☐ Urine														137					
116	Results: 0. — % ☐ Pending				Hazard Class		Placard No.		Results: 0. — % ☐ Pending		Hazard Class		Placard No.												138					
04	50. Carrier No.				51. GVWR / GCWR (trucks & buses only)				80. Carrier No.		81. GVWR / GCWR (trucks & buses only)														139					
—	☒ USDOT 0 7 1 8 2 1				☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ USDOT —				☒ None		☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.						140					
02	☐ MC/MX —				☒ ≥ 26,001 lbs.				☐ MC/MX —																141					
117	52. Motor Carrier or Government Entity				53. Motor Carrier or Government Entity				54. Motor Carrier or Government Entity																142					
—	YRC Worldwide				YRC Worldwide				YRC Worldwide																143					
118	Number & Street				Number & Street				Number & Street																144					
—	10990 ROE AVE				10990 ROE AVE				10990 ROE AVE																145					
119	City				State		Zip		City				State		Zip										146					
—	Overland Park				KS		66211		Overland Park				KS		66211										147					
120	135. Damage to Other Property				☐ Yes (If Yes, describe)		☒ No																				148			
121	Oper.				136. Charge		137. Summons No.		Oper.				138. Charge		139. Summons No.										149					
—	01				39:4-77		1506T163632		—				—		—										150					
122	Oper.				140. Charge		141. Summons No.		Oper.				142. Charge		143. Summons No.										151					
—	—				—		—		—				—		—										152					
123	83				84		85		86		87		88		89		90		91		92		93		94		95		Names & Addresses of Occupants	
124	A				01		01		—		47		M		—		—		01		11		04		—		—		If Deceased, Date & Time of Death	
125	B				02		01		—		03		55		M		05		03		02		11		11		04		Christopher C Beggs	
126	C																												91 DOE COURT BRICK TOWNSHIP NJ 08723	
127	D																												Michael Anthony Kluxen	
128																													1219 LEWIS RD Point Pleasant Borough NJ 08742	

New Jersey Police Crash Investigation Report												Case Number 2019-00071853			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed that Vehicle #1 was making a right turn from the Laurel Square Shopping Center (1930 Rt. 88) onto Rt. 88 westbound. Vehicle #2 was traveling eastbound on Rt. 88, approaching the entrance/ exit of Laurel Square.

It is believed that as Vehicle #1 made the right turn, its rear tire on trailer struck the curb. As the vehicle was turning, the trailer separated from the cab and entered the eastbound lane, striking Vehicle #2. The cab continued forward and pulled to the shoulder of the roadway.

As a result of the impact, Vehicle #2 had major damage. The driver of Vehicle #2 (Michael Kluxen) was seriously injured and had a large laceration to his head. He complained of chest pains and it was later determined that he had 8 broken ribs. The driver of Vehicle #2 was initially transported to Brick Hospital and later transferred to Jersey Shore Medical Center

Vehicle #1 had no damage to the cab and minor damage to the trailer. The trailer had damage on the front end, drivers side. Vehicle #2 had major damage to the drivers side, front end. The cab of Vehicle #1 was driven into the parking lot of Laurel Square and the New Jersey State Police were requested to examine the vehicle. The trailer was towed from the scene by Joe's Service Center. Vehicle #2 was towed by Legacy Towing.

A representative from the NJSP responded to assist us with examining the cab and trailer. The fifth wheel

146. Officer's Signature Joseph J Farnkopf	147. Badge # 173	148. Reviewer Keith Donnelly	Badge # 212	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01
Station: — Case No: 2019-00071853

145 Crash Description

hitch system was checked and found to be in the unlocked or open position while the air lock switch in the cab was in the locked position. The driver of Vehicle #1 advised us that he did a vehicle check this morning and he found nothing wrong with the vehicle. He stated that the fifth wheel was locked this morning and that he traveled numerous miles in stop and go traffic without any issues. He stated that he made several deliveries without any problems with the trailer and that he was with his vehicle the entire day. It could not be determined how the fifth wheel hitch became unlocked and the system appeared to be in working condition. A mechanic from YRC responded to the scene and could not find any defects with the fifth wheel system. He advised me that it is not uncommon for the lock to open and that he has observed incidents like this in the past with this type of truck.

#24/ #25. Vehicle #1 is covered by out of state insurance provided by Old Republic Insurance Co. with a policy number of MWML18562 (exp. 3/01/20).

#38/ #39. Vehicle #1 is a Volvo truck, unknown model.

Joseph J Farnkopf


173

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00071853

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph J Farnkopf

Officer's Signature

173

Badge Number