

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00057385			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

My investigation revealed the following:

Vehicle 1 was traveling North on Truman Dr. approximately 50 feet from Route 88. Vehicle 1 was pulling a 2016 black enclosed trailer bearing New Jersey registration TFU23J. Vehicle 2 was legally parked on the side of the road, unoccupied, and facing North. Driver 1 attempted to park vehicle 1 on the side of the road in front of vehicle 2. The trailer being pulled by vehicle 1 did not have proper clearance and struck vehicle 2.

Driver 1 stated he was attempting to park along the side of the road. He believed he had enough clearance and did not realize he was too close to vehicle 2 until the crash occurred.

No part of vehicle 1 contacted vehicle 2 It was only the trailer being pulled that made contact. The trailer suffered minor damage to the area surrounding the passenger side wheels.

Based upon the above circumstances I find driver 1 to be at fault for the crash.


146. Officer's Signature Anthony Barlowski	147. Badge # 284	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00057385

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale



Truman Dr.

Anthony Barlowski

Officer's Signature

284

Badge Number