

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2021-00056394					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle, same direction (rear-end) crash. Vehicle 2 was stopped in traffic on

Route 88 W just east of Van Zile Road. Vehicle 1 was traveling directly behind vehicle 2 on route 88 W.

The driver of vehicle 1 stated she observed vehicle 2 stopped in front of her at which point she began slowing

down. The driver of vehicle 2 stated she was distracted by food on her hands as she was slowing down and as

result, was unable to come to a stop behind vehicle 2. As a result of the driver of vehicle 1 not being able to

stop in time, the front end of vehicle 1 crashed into the rear end of vehicle 2.

No injuries were reported. Both vehicles sustained damage and were both driven from the scene. The driver of

vehicle 1 is at fault for the crash.


146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Thomas P Caulfield	235	Paul J Catalina	229	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00056394

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Thomas P Caulfield

Officer's Signature

235

Badge Number