

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00054136			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred on Olden Street, approximately 100 feet east of Route 88.

Driver 1 stated that they were making a left turn out of the Home Depot parking lot on to Olden Street when they struck Vehicle 2 which was traveling west on Olden Street.

Driver 2 stated they were traveling west on Olden Street when Vehicle 1 struck them.

Vehicle 1 had minor damage to the front grill area. Vehicle 2 had moderate damage to the passenger side doors.

Both vehicles were removed from the scene by the owners.

My investigation revealed Driver 1 was turning left out of the parking lot and struck Vehicle 2 which was traveling west on Olden Street. Driver 1 is the at fault driver for failure to yield and driver inattention.

146. Officer's Signature Jeffrey Kenneth Maehl	147. Badge # 310	148. Reviewer Keith Prendeville	Badge # 223	149. Case Status ☐ Pending ☒ Complete
---	---------------------	------------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2021-00054136

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

HOME DEPOT
1722 ROUTE 88

Not To Scale



Jeffrey Kenneth Maehl

Officer's Signature

310

Badge Number