

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00060438			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed the following:

The driver of V2 (Vehicle 2) was traveling east on Route 88 and was approximately one hundred yards east from the intersection of Route 88 / Van Zile Road. The driver of V2 then came to a complete stop, activated their left turn signal and was awaiting for traffic to clear in order to make a left turn north onto Old Squan Road.

The driver of V1 (Vehicle 1) was traveling directly behind V2. The collision occurred when the driver of V1 did not observe V2 stopped in traffic with their turn signal activated and impacted the rear end of V2. On scene I observed damage to the front end of V1 and rear end of V2.

The driver of V2 stated she was stopped in traffic with her left turn signal activated and was attempting to make a left turn onto Old Squan Road. While awaiting to make the left turn she was rear ended by the driver of V1. The driver of V1 stated that she did not observe V2's left turn signal activated, which caused her to impact / rear end V2.

146. Officer's Signature Kevin A Docherty	147. Badge # 275	148. Reviewer Keith Prendeville	Badge # 223	149. Case Status ☐ Pending ☒ Complete
--	---------------------	------------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01
Station: — Case No: 2021-00060438

145 Crash Description

The driver of V1 stated she was uninjured and declined first aid treatment. The driver of V2 stated she was concerned for her well-being because she is pregnant and requested first aid. Shortly thereafter, Brick Medical Unit #537 responded to said location in order to check on the well-being of driver 2. Driver 2 was ultimately transported to the Brick Hospital for abdominal pain. The driver of V1 was issued a motor vehicle citation for the following: Careless Driving, 39:4-97, E21-006110. The driver of V2 was also provided with a Brick Township Police Department victim / injury subpoena.


Kevin A Docherty

275

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00060438

144 Crash Diagram (NOT TO SCALE)



Kevin A Docherty

Officer's Signature

275

Badge Number