

NJTR-1 (Rev. 01/17)[illegible]

New Jersey Police Crash Investigation Report												Case Number 2021-00061074			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was turning right onto Route 88 from the parking lot of 2075 Route 88. Vehicle 2 was starting in traffic on Route 88 in the area of Midstreams Road. Vehicle 1 failed to yield the right of way to Vehicle 2, causing the crash.

Driver 1 stated the following: he was making a right turn from the parking lot of 2075 Route 88, trying to access Route 88. He thought Driver 2 was allowing him to pull out of the parking lot, when Vehicle 2 started to move and struck the rear of his vehicle.

Driver 2 stated the following: she was starting in traffic on Route 88 in the area of Midstreams Road. When she began to go she never saw Vehicle 1 pulling out of the parking lot of 2075 Route 88 and struck Vehicle 1.


There was no reported injuries on scene. Both Vehicles were moved prior to my arrival. Both Vehicles were driven from the scene by their respected drivers.

146. Officer's Signature Christopher R Joaquim	147. Badge # 271	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00061074

144 Crash Diagram (NOT TO SCALE)



Christopher R Joaquim

271