

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00055123			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling in the rear of Home Depot, located at 1722 Route 88. Vehicle #2 was parked in a legal parking space to the rear of Home Depot.

Driver #1 stated he made his delivery and was attempting to leave the lot. He was traveling eastbound behind the building when he came to a hard right hand turn. He was unable to make the turn first try so he backed up a little bit and began to pull forward once again. Unknown to Driver #1, the rear of his trailer hooked the aluminum utility body of Vehicle #2 and when he began to pull forward, he began to drag Vehicle #2 approximately 16" east. A small scratch to the semi-trailer was observed. Very minor damage to both vehicles was observed.

A small scratch to the raw aluminum body was observed on vehicle #2 where the trailer pulled the truck in the spot. A rubber drag mark from the rear tire of Vehicle #2 was observed on scene to show how far Vehicle #2 moved.

Based on my observations and the statement made by Driver #1, he was determined to be at fault for the crash.

146. Officer's Signature Joseph W McGrath	147. Badge # 277	148. Reviewer Glenn C Turner	Badge # 178	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00055123

145 Crash Description

*Vehicle 1 Box #25:

National Union Fire Ins Co of Pittsburgh

Aon Risk Services Central Inc.

200 East Randolph

Chicago, IL 60601

(312) 381-1000

TRAILER INFO:

Owner: Exel Inc.

300 S. Salem Church Rd.

York, PA 17408

2018 Strick 53 ft cargo box

white

registration: Oklahoma BG7916

Expires 12/31/2021

Vin# 1S12E9531JE537539

Joseph W McGrath


277

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00055123

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph W McGrath

Officer's Signature

277

Badge Number