

New Jersey Police Crash Investigation Report												Case Number 2020-00006803			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 had backed out of a parking space in the lot of 2030 Rt 88 as Vehicle #2 was pulling into the lot.

Vehicle #1 finished backing and started to drive forward as Vehicle #2 was passing in front of him. Vehicle #1 crashed into the passenger's side of Vehicle #2 after it had entered the lot.

The driver of Vehicle #1 stated that he had just finished backing out of his spot and did not notice that Vehicle #2 had just driven in, as he was checking for oncoming traffic behind him. After backing, The driver of Vehicle #1 stated he then put the car in drive and started to pull forward as Vehicle #2 was entering another parking space, causing the crash.

The driver of Vehicle #2 stated that she had seen Vehicle #1 had backed out of it's space and decided to park in a space opposite of the direction Vehicle #1 was backing. As she pulled into the lot, Vehicle #1 began to drive forward into her as she was parking.

No injuries were reported on scene.

146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer John D Gordon	Badge # 237	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00006803

144 Crash Diagram (NOT TO SCALE)



ScenePD™ - Evaluation Edition

2030 Rt 88 Lot



Rt 88

Trancite (877) 908-4777

Robert F Scelfo

189