

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00050619			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene indicated the following: Vehicle 1 was stopped in traffic at the traffic signal on

Route 70 west approaching Olden Street in the left lane. Vehicle 2 was stopped at the traffic signal in the left

lane, in front of vehicle 1. The traffic signal turned green, vehicle 1 struck vehicle in the rear which caused

minor damage.

I spoke to driver 1 at the scene. She stated that they were stopped in traffic due to the traffic signal. She

stated that the light was green and vehicle 2 had started to move. She stated the vehicle slammed on its brakes

for no reason which caused the accident.

I spoke to driver 2 at the scene. He stated he was stopped in traffic at the light and noticed the person behind

him on the cell phone. Driver 2 stated that he knew she was going to hit him because she was not paying

attention to the roadway.

Based on statements made and damage to the vehicles, it was determined vehicle 1 was the at fault vehicle.

146. Officer's Signature Anthony William Chadwick	147. Badge # 281	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2019-00050619

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Olden Street

NOT TO SCALE



v2

Highway 70

Anthony William Chadwick

Officer's Signature

281

Badge Number