

New Jersey Police Crash Investigation Report												Case Number 2019-00050799			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Two car crash occurred on 8/9/2019 at approximately 1131 hours at the intersection of Route 88 and Midstreams Rd. My body worn camera was on during this investigation.

Driver of vehicle #1, Sharline Smith, advised she was making a left at the traffic light from Midstreams Rd onto Route 88 westbound and did not see vehicle #2 approaching. Smith advised he "came out of nowhere" and hit her as she was turning through the intersection.

Driver of vehicle #2, Nicholas Perez, stated he was coming through the intersection from Coolidge Rd and continuing straight through the intersection to Midstreams Rd. Perez advised the traffic signal was green. Perez advised he saw vehicle #1 begin to turn suddenly through the intersection and left him no time to stop or avoid the collision. Perez stated he struck vehicle #1 in the front right with the front left of his vehicle.

Vehicle #1 was towed (disabled) by Joe's service center and vehicle #2 was left on scene. Perez advised the vehicle seemed drivable but felt some shaking in the steering wheel after moving the vehicle from the intersection.

146. Officer's Signature Matthew C Knehr	147. Badge # 295	148. Reviewer Joseph L Rossi	Badge # 240	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2019-00050799

145 Crash Description

Smith had a dark purple bruise on the back of her right hand. Smith was treated on scene by Brick EMS (Unit 523) and refused further medical attention.

Vehicle #1 had a front driver's airbag deployment.

Vehicle #1 is found to be at fault for failing to yield the right of way to oncoming traffic.

Matthew C Knehr

Officer's Signature

295

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00050799

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Matthew C Knehr

Officer's Signature

295

Badge Number