

**New Jersey Police
Crash Investigation Report**

Case Number

2019-00044418

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Driver #1 stated while backing out of the parking spot, the rear right bumper of her vehicle collided into the front right bumper of vehicle #2. Driver #1 said she did not see vehicle #2 stopped behind her.

Driver # 2 stated she was stopped behind vehicle #1 waiting for a parking spot to become available. Driver #2 said all of a sudden vehicle #1 started to back up, and she attempted to alert driver #1 by applying the vehicles horn with negative results. Vehicle #1 subsequently collided into the front right bumper of vehicle #2 causing a moderate dent.

On scene investigation determined vehicle #1 to be at fault for unsafe backing. Driver #1 was issued a written warning 39:4-97.3 (operation of vehicle in an unsafe manner.)

Both driver were not injured and refused medical attention.

146. Officer's Signature
Richard J Zimmerer

147. Badge #
272

148. Reviewer
Charles P Kelly

Badge #
241

149. Case Status
☐ Pending ☒ Complete


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00044418

144 Crash Diagram (NOT TO SCALE)



WALMART
1872 ROUTE 88



Richard J Zimmerer

272