

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00056456			Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 struck Vehicle #2 while attempting to back out of parking space in the parking lot of 1872 RT 88 Walmart.

Driver of Vehicle #1 stated she backed straight out of her parking space and collided with Vehicle #2. Driver #1 advised she did not observe vehicle #2 behind her. Vehicle #1 had no visible damage.

Driver of Vehicle #2 stated she was at a complete stop at stop sign in the Walmart parking lot. Driver #2 stated as she waited for traffic to pass Vehicle #1 backed out of its parking space and struck her vehicle along the middle of the drivers side. Driver #2 advised she has neck pain but denied medical treatment. Vehicle #2 had no visible damage.

Based on my observations and statements made by both parties I found the driver of Vehicle #1 at fault for backing unsafely.

146. Officer's Signature Frank James Giambona	147. Badge # 290	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
--	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:


Case No: 2019-00056456

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Walmart 1872 RT 88



Frank James Giambona

290