

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00076575			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was leaving the lot of the Laurel Square Plaza (1930 Rt 88) onto Rt 70 west bound, behind Vehicle #2. Vehicle #2 started to exit the plaza but had to stop again for oncoming traffic. The driver of Vehicle #1 did not see Vehicle #2 stop again and crashed into it's rear bumper.

The driver of Vehicle #1 stated that he thought Vehicle #2 had merged onto Rt 70 as he was checking for oncoming traffic. He added that he did not see Vehicle #2 had stopped and crashed into it.

The driver of Vehicle #2 stated that she started to pull out onto Rt 70 but had to stop again when an oncoming vehicle change lanes into the lane she was pulling out into. She added that this was when Vehicle #1 crashed into her.

No injuries were reported on scene.

146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00076575

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Rt 70 E/B



Robert F Scelfo

Officer's Signature

189

Badge Number