

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00064061			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
	02	01	01	—	38	M	—	—	—	11	04	—	—	CHRISTOPH HOLTON 114 STEPHAN RD BRICK TOWNSHIP NJ 08724		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene indicated the following: Vehicle 1 was stopped at the stop sign at the ramp from 70 west to Van Zile Road. Vehicle 2 (a Fedex delivery truck) traveled southbound on Van Zile Road in the left lane approaching route 70. Vehicle 1 attempted to make a left turn to travel northbound on Van Zile Road. As vehicle 1 entered the left southbound lane of Van Zile Road, vehicle 2 struck vehicle 1. Vehicle 1 was towed from the scene. Vehicle 2 received moderate damage but was driven from the scene.

I spoke to driver 1 at the scene. She stated she was making the left turn onto Van Zile Road. She stated that she did not see the Fedex truck and believed he was traveling at a high rate of speed.

I spoke to driver 2 at the scene. He stated he traveled on Van Zile Road when a vehicle entered the lane in front of him and he was unable to avoid the accident.

Based on statements and damage to the vehicles, it was determined driver 1 was at fault.

146. Officer's Signature Anthony William Chadwick	147. Badge # 281	148. Reviewer Paul J Catalina	Badge # 229	149. Case Status ☐ Pending ☒ Complete
--	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00064061

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Anthony William Chadwick

281