

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00061245			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Driver #2 stated she was traveling in the right most lane on Route 70 traveling eastbound. After passing through the intersection of Route 70 and Route 88, Vehicle #1 passed her in the right shoulder and struck the passenger side fender of her car. There was no paint transfer on Vehicle #2 and Driver #2 could not provide a description of the vehicle or driver that struck her except for an older model light colored sedan. The vehicle continued on Route 70 eastbound and then pulled off onto the U-turn ramp for Olden Street. Vehicle #1 was unable to identified or located.

146. Officer's Signature Joseph W McGrath	147. Badge # 277	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2019-00061245

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



NOT TO SCALE



Joseph W McGrath

Officer's Signature

277

Badge Number