

New Jersey Police Crash Investigation Report												Case Number 2019-00062629			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling eastbound on Route 88 when the front of the vehicle collided with the rear of vehicle 2 which was stopped in traffic on Route 88 near Brentwood Ave.

The driver of vehicle 1 advised he was traveling east bound on Route 88 when he dropped something. The driver advised he reached down to grab the item and upon looking back at the road he observed vehicle 2 stopped in traffic in front of his vehicle. The driver advised he attempted to slow down and swerve around the vehicle however was unable to do so causing the front of his vehicle to collide with the rear of vehicle 2.

The driver of vehicle 2 advised he was stopped on Route 88 attempting to make a left turn onto Brentwood Ave when the driver of vehicle 1 collided with the rear of his vehicle.

Vehicle 1 sustained damage to the front while vehicle 2 sustained damage to the rear. There were no reported injuries at the time of this report.

146. Officer's Signature Daniel P Kenny	147. Badge # 253	148. Reviewer Paul J Catalina	Badge # 229	149. Case Status ☐ Pending ☒ Complete
--	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00062629

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Daniel P Kenny

Officer's Signature

253

Badge Number