

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 2019-00065133				Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was stopped behind Vehicle 2 at a yield sign on the ramp from RT 88 to RT 70wb. Vehicle 2 started forward but stopped again due to oncoming traffic. Vehicle 1 started forward with Vehicle 2, but failed to stop again and crashed into the rear of Vehicle 2.

Driver 1 and Driver 2 both stated same as above. Driver 1 admitted fault for the crash and added, going forward, he will make sure the vehicle in front of him fully merges into traffic before proceeding.

No injuries were reported by either party and both vehicles were driven from the scene. No motor vehicle summonses were issued.

146. Officer's Signature Daniel P Testa	147. Badge # 265	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2019-00065133

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



Daniel P Testa

Officer's Signature

265

Badge Number