

New Jersey Police Crash Investigation Report												Case Number 2019-00068592			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was turning left out of 410 Route 88 onto Route 88 eastbound, East of Fort St. Vehicle #2 was traveling West on Route 88. Vehicle #1 pulled out in front of vehicle #2 causing vehicle #2 to strike the driver side of vehicle #1. The driver of vehicle #2 had a complaint of chest pain and EMS responded to the scene. The driver of vehicle #2 later refused medical attention. No other injuries were reported on scene.

Driver of Vehicle #1 stated he was making a left hand turn onto Route 88 East, saw the roadway was clear and began to make his turn. While making the left turn, Vehicle #2 turned right onto Route 88 West and was coming at a high rate of speed and struck his vehicle.

Driver of Vehicle #2 stated he was traveling West on Route 88 when Vehicle #1 turned out in front of his vehicle and could not brake in time and struck Vehicle #1.

A witness, later identified as Olivia Duffey stated that she observed Vehicle #1 try to make the turn and came out in front of Vehicle #2 and Vehicle #2 could not stop in time.

146. Officer's Signature Edward McCaffery	147. Badge # 298	148. Reviewer Michael V Feeney	Badge # 200	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: — Case No: 2019-00068592

145 Crash Description

In conclusion of my investigation vehicle #1 was found to be at fault for failing to yield the right of way to vehicle #2 and causing the accident. Driver #1 was issued a summons for 39:4-97.

Driver #1 was not injured but due to airbag deployment he was checked by First Aid and refused medical attention.

Edward McCaffery


298

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00068592

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Edward McCaffery

298