

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00058507			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: Vehicle #2 was facing north and was stopped in the right lane at the Route 70 exit ramp. Vehicle #1 was traveling directly behind Vehicle #2. The collision occurred when the driver of Vehicle #1 failed to come to a complete stop and impacted the rear end of Vehicle #2. On scene I observed damage to the front end of Vehicle #1 and rear end of Vehicle #2.

The driver of Vehicle #2 stated he was stopped when the rear of his vehicle was impacted by Vehicle #1. The driver of Vehicle #1 stated the rear end of her vehicle was struck by an unknown black passenger car (suspect vehicle # 3), which caused her to roll forward into Vehicle #2. She stated she did not have any additional information regarding the alleged Vehicle #3. Let it be noted the driver of Vehicle #2 stated there was not a third vehicle involved in the crash.

The driver of Vehicle #2 had a complaint of chest pain and was treated by Brick Medical Unit #537 at the scene. The driver of Vehicle #1 declined first aid attention. The driver of Vehicle #1 was issued a motor vehicle citation for following too closely (39:4-89, E19-005574).

146. Officer's Signature Andriy Shevchuk	147. Badge # 294	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00058507

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Andriy Shevchuk

294