



| New Jersey Police<br>Crash Investigation Report |    |    |    |    |    |    |    |    |    |    | Case Number<br>2019-00067126 |    |    |                                                                                | Page <u>2</u> of <u>4</u> |  |
|-------------------------------------------------|----|----|----|----|----|----|----|----|----|----|------------------------------|----|----|--------------------------------------------------------------------------------|---------------------------|--|
|                                                 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93                           | 94 | 95 | Names & Addresses of Occupants<br><i>If Deceased, Date &amp; Time of Death</i> |                           |  |
| E                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |
| F                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |
| G                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |
| H                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |
| I                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |
| J                                               |    |    |    |    |    |    |    |    |    |    |                              |    |    |                                                                                |                           |  |

144. Crash Diagram



Show NORTH by Arrow  
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation revealed vehicle two was traveling westbound on State Highway 88 and vehicle one was merging onto the roadway from the parking lot of 1872 State Highway 88 (Walmart). As vehicle one was merging onto the roadway, its driver side front fender was struck by the driver side front bumper of vehicle two.

Upon arrival, both vehicles remained in the roadway. State Highway 88 was closed in both directions from Post Road to Jack Martin Boulevard for the duration of the investigation. Driver two suffered from a possible dislocated ankle and required medical attention. Driver one was trapped inside his vehicle and had complaint of pain in the area of his left hip. Brick Township Fire Station #23 was dispatched to the scene to extricate driver one from his vehicle. Driver two was transported to Ocean Medical Center by Emergency Medical Services Unit #538, and driver one was transported to Jersey Shore Medical Center by Emergency Medical Services Unit #536.

Vehicle one sustained disabling damage to its driver side, toward the front end; and vehicle two sustained disabling damage to its front end, toward the driver side. Vehicle one was towed from the scene by Brick Performance, and vehicle two was towed from the scene by Andrew's Auto Body.

|                                            |                     |                                  |                |                                                                                                   |
|--------------------------------------------|---------------------|----------------------------------|----------------|---------------------------------------------------------------------------------------------------|
| 146. Officer's Signature<br>Kyle W Patrick | 147. Badge #<br>296 | 148. Reviewer<br>Neal R Pedersen | Badge #<br>160 | 149. Case Status<br><input type="checkbox"/> Pending <input checked="" type="checkbox"/> Complete |
|--------------------------------------------|---------------------|----------------------------------|----------------|---------------------------------------------------------------------------------------------------|

# New Jersey Police Crash Investigation Report

## Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: — Case No: 2019-00067126

## 145 Crash Description

Driver one stated he was exiting the Walmart parking lot. He stopped at the stop sign and checked the roadway before attempting to turn right onto State Highway 88 westbound. Drive one did not see vehicle two approaching him as the front end of his vehicle entered the roadway. At this time, vehicle two's front end struck the driver side of vehicle one.

Driver two stated she was traveling westbound on State Highway 88. As she approached the exit of the Walmart parking lot, she observed vehicle one stopped at the stop sign without utilizing a turn signal. Driver two continued traveling straight ahead when vehicle one sped out in front of her to make a left turn onto State Highway 88 eastbound. Despite her "slamming" on the brakes, driver two did not have the time or distance to react and her front end struck vehicle one.

No witnesses observed the motor vehicle accident, but based on my investigation I determined driver one to be at fault. The damage on both vehicles suggested driver one was attempting to make a left turn out of the parking lot, which was not allowed at that specific exit. Regardless of whether driver one was attempting to make a left or right turn out of the Walmart parking lot, he failed to yield to vehicle two, which was established in the roadway. Driver one was not attentive to his surroundings, otherwise he would have observed vehicle two before attempting to enter the roadway. Driver one was issued the following summonses:

- Failure to Yield (39:4-144) on summons E19-006308
- Careless Driving (39:4-97a) on summons E19-006309

Kyle W Patrick


296

New Jersey Police Crash Investigation Report  
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01  
Station:        Case No: 2019-00067126

144 Crash Diagram (NOT TO SCALE)

○ Indicate  
North



Kyle W Patrick

Officer's Signature

296

Badge Number