

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00032133			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling East on Route 88. Vehicle #2 was traveling South on Olden Street. At the intersection of Route 88 / Olden street the front end of Vehicle #1 crashed into the left middle of Vehicle #2. Driver #1 stated that she was traveling on Route 88 East and the traffic light was green. When Vehicle #2 appeared in the intersection, Driver #1 stated that she did not have sufficient time to stop to avoid the crash. Driver #2 stated that she was traveling south on Olden Street and the traffic light was also green. She stated that when she was crossing intersection her Vehicle #2 was impacted by Vehicle #1. After conducting our investigation, it was determined that Driver #1 was at fault. Both drivers were advised of report/complaint procedures. The front passenger from Vehicle #2 complaint of pain and was hospitalized. Vehicle #1 was towed by Lepore Enterprises and Vehicle #2 was towed by Joe and Sons Towing.

146. Officer's Signature Andriy Shevchuk	147. Badge # 294	148. Reviewer John D Gordon	Badge # 237	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00032133

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Andriy Shevchuk

Officer's Signature

294

Badge Number