

NJTR-1 (Rev. 01/17)[illegible]

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2019-00029489					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 made a right turn on a red traffic signal from Jordan Rd onto Rt 88 E/B before going out of control on the wet pavement and crashing into a guide rail fence

The driver of Vehicle #1 stated that there was another vehicle oncoming and that he accelerated which caused his vehicle to go out of control due to the weather conditions and crashed into the guide rail face.

No injuries were reported on scene.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Robert F Scelfo	189	Anthony S DeMaio	194	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00029489

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Robert F Scelfo

Officer's Signature

189

Badge Number