

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00047129			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was parked in front of Atlantic Medical Imaging (AMI), 455 Jack Martin Boulevard, in the parking lot, not in a parking spot. Vehicle 2 was a commercial truck where the driver was actively loading and unloading laundry for AMI through his employer, Image First Healthcare Laundry Specialists. Vehicle 2 was too large to be able to park in a parking spot or anywhere else and would commonly park in this location to load and unload.

Vehicle 1 was backing out of a parking spot on the same side of the building and backed up into vehicle 2.

Driver 1 stated vehicle 2 was parked next to the building and she was parked in a parking spot on the same side of the building. Driver 1 stated she began to back up out of the parking spot and backed up into vehicle 2.

Driver of vehicle 2 stated he was away from his vehicle, inside AMI, when driver 1 came into the business inquiring about who drove the truck parked to the side of the business. Driver of vehicle 2 stated he came outside and driver 1 advised him that she backed up into his vehicle.

Investigation revealed that the cause of the crash was due to multiple factors. First, vehicle 2 was parked outside a legal parking spot, unable to park in a marked spot, due to the size of the vehicle. Second, driver 1

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	----------------------------	--	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2019-00047129

145 Crash Description

failed to observe her proximity to vehicle 2 as she was backing out of the parking spot, causing her vehicle to collide with vehicle 2.

Michael A DeFluri

Officer's Signature

270

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00047129

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Michael A DeFluri

270