

[illegible]

New Jersey Police Crash Investigation Report												Case Number 2019-00063083			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was attempting to turn left from 415 Jack Martin Blvd to travel northbound on Jack Martin Blvd. Vehicle 2 was traveling southbound on Jack Martin Blvd. Vehicle 1 entered the roadway causing a right angle collision with vehicle 2.

The driver of vehicle 1 advised she was attempting to turn left from 415 Jack Martin Blvd to travel northbound on Jack Martin Blvd. Driver 1 advised she entered the roadway then collided with vehicle 2.

The driver of vehicle 2 advised she was traveling southbound on Jack Martin Blvd. Driver 2 advised other vehicles pulled to the shoulder to turn right into the parking lot of 415 Jack Martin Blvd. Driver 2 advised she continued in her lane of travel when vehicle 1 entered the roadway causing a right angle collision with her vehicle.


146. Officer's Signature Chase S Carter	147. Badge # 280	148. Reviewer Joseph L Rossi	Badge # 240	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00063083

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Chase S Carter

Officer's Signature

280

Badge Number