

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2020-00033964					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 is a FedEx delivery box truck that struck the overhead canopy of the Complete Care of Laurelton building (475 Jack Martin Blvd 732-458-6600).

The driver of Vehicle #1 stated that he believed he had enough overhead space to park the truck under the canopy. As he did so, he stated the top of the box truck crashed into the top of the bay roof.

No injuries were reported on scene.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Robert F Scelfo	189	Joseph T Pacitti	238	☐ Pending ☒ Complete



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00033964

144 Crash Diagram (NOT TO SCALE)



Complete Care of Laurelton Lot 475 Jack Martin Blvd



Robert F Scelfo

Officer's Signature

189

Badge Number