

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00046507			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was attempting to park in the lot of the Wendy's restaurant (101 Jack Martin Blvd) when it jumped the curb, ran over small bushes and careened off of a tree.

The elderly driver of Vehicle #1 stated that she must have pressed on the accelerator instead of the brake which caused the crash.

No injuries were reported on scene and AAA was called by the driver/ registered owner to remove the van from the wooded area.


146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00046507

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Wendy's
101 Jack Martin Blvd

Robert F Scelfo

Officer's Signature

189

Badge Number