

NJTR-1 (Rev. 01/17)


**New Jersey Police
Crash Investigation Report**

Case Number
2019-00027406

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was parking in the parking lot of Walmart, 1872 Rt 88. Vehicle 1 attempted to park in a spot next to

Vehicle 2. Vehicle 1 struck vehicle 2 then left the scene of the collision. This was observed on video

surveillance footage from Walmart. I was unable to obtain a license plate number due to video quality, however

the vehicle is a silver Ford Escape or Mazda Tribute.

146. Officer's Signature
Chase S Carter

147. Badge #
280

148. Reviewer
William Vendrell

Badge #
228

149. Case Status
☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01



Station:

Case No: 2019-00027406

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Walmart 1872 Rt 88



Chase S Carter

Officer's Signature

280

Badge Number