

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00022695			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

My investigation revealed the following:

Vehicle 1 was traveling east on Route 88 approaching the intersection with Burrsville Rd. Vehicle 2 was traveling east on Route 88 directly in front of vehicle 1. Vehicle 2 applied the brakes which caused vehicle 1 to crash into the rear of vehicle 2.

Driver 1 stated he was traveling in the area of the interchange on Princeton Ave. and pulled into the right lane to wait for the light to turn green. He stated vehicle 2 was to the left of him in the left lane. When the light turned green he accelerated and got in front of vehicle 2. Driver 1 believes this angered driver 2. Driver 2 began to drive aggressively behind him. Driver 2 then accelerated on the shoulder and passed vehicle 1. Just as vehicle 2 got in front of vehicle 1, driver 2 slammed on his brakes. Driver 1 stated there was no way for him to avoid the collision and believes driver 2 caused the crash on purpose.

Driver 2 stated he was traveling on Route 88 and was behind vehicle 1. Vehicle 1 was traveling slowly so he passed it in a designated passing area. He continued to drive and hit the brakes because he was attempting to

146. Officer's Signature Anthony Barlowski	147. Badge # 284	148. Reviewer Neal R Pedersen	Badge # 160	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2019-00022695

145 Crash Description

find the correct street to turn down and was lost. When he did this vehicle 1 drove onto the shoulder and attempted to pass him. Driver 2 continued driving on route 88 and vehicle 1 went back behind him. Driver 2 stated vehicle 1 then began tailgating him and making aggressive movements with his vehicle. As he approached the intersection with Burrsville Rd. he hit the brakes again to navigate the curve in the road. When he hit the brakes he was struck in the rear by vehicle 1.

There was no debris field, or other evidence, in the road and no witnesses to the incident. Based off of the contradicting statements made by both drivers I am unable to determine who is at fault for the crash.

Anthony Barlowski

Officer's Signature

284

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00022695

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Anthony Barlowski

Officer's Signature

284

Badge Number