

New Jersey Police Crash Investigation Report												Case Number 2019-00024834			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was slowing behind Vehicle #2 on Rt 70 W/B in the turn lane for Brick Blvd. Vehicle #1 did not slow in time to avoid crashing into the rear of Vehicle #2.

The driver of Vehicle #1 stated that she attempted to stop behind Vehicle #2 in the inside left turn lane for Brick Blvd S/B. As she slowed, she stated that she realized that she did not have enough space in front of her to keep from crashing into Vehicle #2's rear bumper.

The driver of Vehicle #2 stated he was rear ended by Vehicle #1 as he was stopped in traffic.

No injuries were reported on scene.



146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00024834

144 Crash Diagram (NOT TO SCALE)

 Indicate North



Rt 70 W/B

Robert F Scelfo

Officer's Signature

189

Badge Number