

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00026270			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling west on RT 88 approaching the area of J's Garden Spot (2039 RT 88). Vehicle 1 exited the parking lot of J's Garden Spot, traveled north across RT 88 towards the entrance to the mulch yard, and crossed in front of Vehicle 2, causing Vehicle 2 to crash into the right middle of Vehicle 1.

Driver 1 stated she had just finished paying for a load of mulch and was waiting for a break in traffic to exit the parking lot of J's Garden Spot. Driver 1 stated the mulch was in the lot directly across the street, and after an unknown vehicle traveling east on RT 88 stopped in traffic to let her out she started forward into the roadway. Driver 1 stated she looked to her right for oncoming westbound traffic and observed Vehicle 2 far off in the distance. Driver 1 stated she felt Vehicle 2's distance was far enough that it would be safe for her to continue across RT 88 into the mulch lot. Driver 1 stated as she proceeded forward it appeared Vehicle 2 was travelling much faster than she anticipated and ultimately crashed into her before she could finish crossing the roadway.

Driver 2 stated he was traveling west on RT 88 when he observed Vehicle 1 pulling out of the parking lot of J's Garden Spot. Driver 2 stated when Vehicle 1 initially stopped pulling forward, he figured Driver 1 saw he was

146. Officer's Signature Daniel P Testa	147. Badge # 265	148. Reviewer Lawrence Petrola	Badge # 201	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2019-00026270

145 Crash Description

approaching and would remain stopped. When Vehicle 1 instead proceeded forward, crossing into his lane, he was unable to stop or avoid a collision.

As a result of the crash, Driver 1's upper lip struck her steering wheel and split open, causing it to bleed.

Brick EMS responded to the scene and Driver 1 was transported to Brick Hospital for further treatment. Also as a result of the crash, Vehicle 2's front air bags deployed and Driver 2 had a complaint of chest pain. Driver 2 refused medical attention while on scene and advised me he may respond to the hospital later on his own if the pain gets worse. Both vehicle's were disabled as a result of the crash and towed from the scene.

My on scene investigation determined Driver 1 to be at fault for the crash and she was subsequently issued a Careless Driving summons (# E19 002160)

Daniel P Testa


265

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00026270


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE

J's Garden Spot
2039 RT 88



J's Garden Spot
Mulch Lot

Daniel P Testa

Officer's Signature

265

Badge Number