

New Jersey Police Crash Investigation Report												Case Number 2019-00017764			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation concluded: Vehicle #1 and #2 were traveling on the jug handle from Rt. 70 Eastbound attempting to enter Van Zile Rd. Vehicle #2 stopped at the stop sign prior to entering Van Zile Rd. due to traffic. Vehicle #1 failed to observe Vehicle #2 stopped and struck the rear of Vehicle #2. Driver of Vehicle #1 is at fault.

Driver of Vehicle #1 advised he was traveling on the jug handle from Rt. 70 to Van Zile Rd. when he began to slow as he approached Van Zile Rd. Driver of Vehicle #1 relayed he was looking at traffic on Van Zile Rd. and failed to observe Vehicle #2 stopped at the stop sign. Driver of Vehicle #1 advised he struck the rear of Vehicle #2 and it was his fault.

Driver of Vehicle #2 stated she was stopped at the stop sign on the jug handle from Rt. 70 onto Van Zile Rd. when her vehicle was struck in the rear by Vehicle #1.

146. Officer's Signature James M Albanese	147. Badge # 257	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00017764

144 Crash Diagram (NOT TO SCALE)



RT. 70
EASTBOUND



James M Albanese

Officer's Signature

257

Badge Number