

New Jersey Police Crash Investigation Report												Case Number 2019-00019507			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred on Van Zile Road approximately 200 feet south of the intersection to Route 70.

Driver of Vehicle #1 advised he was stopped on Van Zile Road, looked down and rolled into Vehicle #2. Driver #1 advised he struck the rear of Vehicle #2.

Driver of Vehicle #2 advised she was stopped on Van Zile Road at the traffic signal. Driver #2 advised she was struck from behind by Vehicle #1.

There were no reported injuries while on scene.

Vehicle #1 struck the rear of Vehicle #2. There was two small marks on the rear bumper of Vehicle #2 from where the screws to the license plate holder struck the vehicle. There was no damage to Vehicle #1.

Driver #1 is the at fault driver for following too closely and driver inattention.

146. Officer's Signature Brian R Foley	147. Badge # 247	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2019-00019507

145 Crash Description

Brian R Foley

Officer's Signature

247

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2019-00019507

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Brian R Foley

Officer's Signature

247

Badge Number