

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00053951			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation concluded: Vehicle #1 and #2 were traveling in the parking lot of 459 Jack Martin Blvd.

when Vehicle #1 began to back out of a parking stall. Vehicle #2 was traveling in the lane of travel within the parking lot, observed Vehicle #1 back out of the parking stall and attempted to avoid Vehicle #1. Vehicle #1 failed to observe Vehicle #2 traveling in the lot and struck Vehicle #2 as it backed out. Vehicle #1 is at fault.

Driver of Vehicle #1 advised she was backing out of a parking stall and did not observe Vehicle #2 traveling in the lot. Driver of Vehicle #1 advised she backed up and hit Vehicle #2.

Driver of Vehicle #2 advised she was traveling in the parking lot when Vehicle #1 quickly backed out of parking stall in front of her vehicle. Driver of Vehicle #2 advised she attempted to avoid Vehicle #1 but was hit by Vehicle #1 as she attempted to stop.


146. Officer's Signature James M Albanese	147. Badge # 257	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram




Police Dept: Brick Police Code: 01
Station: Case No: 2020-00053951

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



459 JACK MARTIN
BLVD.



James M Albanese

Officer's Signature

257

Badge Number