

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00014858			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling westbound on Route 88 approaching the intersection of Burrsville Road. Vehicle #2 was traveling southbound on Burrsville Road approaching the intersection of Route 88.

Driver #1 stated she was continuing on Route 88 so she utilized her left blinker to advise the drivers on Burrsville Road. As she was passing the intersection she stated Vehicle #2 did not stop at the stop sign and came into her lane of travel. Driver #1 was unable to stop her vehicle before making contact with Vehicle #2.

Driver #2 stated she pulled up and stopped at the stop sign and began to slightly inch out in the intersection when Vehicle #1 struck the left front of her vehicle.

A witness remained on scene and completed a Witness Statement Form. The witness stated he was driving behind Vehicle #1 and observed her utilized the proper signal before Vehicle #2 did not stop at the stop sign. He stated Vehicle #2 came into the intersection in front of Vehicle #1, which attempted to stop but began to slide into Vehicle #2, due to the wet roadway.

146. Officer's Signature Joseph W McGrath	147. Badge # 277	148. Reviewer Paul J Catalina	Badge # 229	149. Case Status ☐ Pending ☒ Complete
--	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: Case No: 2019-00014858

145 Crash Description

Based on statements made by both drivers, the witness, as well as, my on scene observations, I determined Vehicle #2 to be at fault for the crash. The vehicles were still in the roadway upon my arrival, along with a pile of debris that was in the lane of travel on Route 88 westbound.

Joseph W McGrath

Officer's Signature

277

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: —

Case No: 2019-00014858

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph W McGrath

Officer's Signature

277

Badge Number