

96	Page 1 of 4		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a																																																																																																																																																						
05	1. Case Number 2019-00008921										10. Crash Occurred On: JACK MARTIN BLVD										11. Speed Limit 4 5		12. Route No. Suffix		13. Milepost		20																																																																																																																																																
01	2. Police Dept. of Brick Police										Code 01		Road Name Dir														36																																																																																																																																																
06	3. Station/Precinct												At Intersection with ☒ Feet ☒ N ☐ E ☐ Miles ☐ S ☐ W										of: Frank Neri Dr		18. Speed Limit 2 5		25																																																																																																																																																
05	4. Date of Crash mm dd yy 0 2 1 9										5. Day of Week Su M Tu W Th F Sa 11		6. Time (use 2400 hrs.) 1 9 2 7		7. Municipality Code 1 5 0 6		8. Total Killed -		9. Total Injured 0 2		19. Ramp To: 17. Cross Road Name/Route No. From: -		21. Latitude 22. Longitude		119b																																																																																																																																																		
01	23. Veh. # 4039-06-66-69										24. Policy No. 148		25. NJ Ins. Code 148										53. Veh. # 02		54. Policy No. AS7-Z11-260496-027		55. NJ Ins. Code 23043		120a																																																																																																																																														
04	26. Driver's First Name DANIELLE										Initial M		Last Name DEMERS										29. Sex F		56. Driver's First Name SHARON		Initial J		Last Name CHESTER										59. Sex F		120b																																																																																																																																		
02	27. Number & Street 2 CHERRYWOOD CIR										28. City BRICK TOWNSHIP										State NJ		Zip 08724		57. Number & Street 56 JOSEPH BYRNE DR		58. City BRICK TOWNSHIP										State NJ		Zip 08724		121a																																																																																																																																		
02	30. Eyes 0 5										DL Class D		Restrictions -										Endorsements -		31. State NJ		60. Eyes 0 2		DL Class D		Restrictions -										Endorsements -		61. State NJ		121b																																																																																																																														
02	32. Driver's License Number D 2 4 6 1 1 5 3 7 4 6 1 8 7 5										33. DOB mm dd yy 1 1 1 6 8 7		34. Expires mm yy 1 1 2 0		62. Driver's License Number C 3 4 0 2 7 0 3 7 1 6 1 6 3 2										63. DOB mm dd yy 1 1 1 0 6 3		64. Expires mm yy 1 1 1 9												122																																																																																																																																				
04	35. Owner's First Name Same as Driver RICHARD DEMERS										Initial Last Name										65. Owner's First Name Same as Driver FM Howell&Co Inc.										Initial Last Name										07																																																																																																																																		
01	36. Number & Street 804 MARBRO AVE										37. City BRICK TOWNSHIP										State NJ		Zip 08724		66. Number & Street 79 PENNA AVE										67. City Elmira										State NY		Zip 14904		124																																																																																																																										
01	38. Make Nissan										39. Model Sentra										40. Color WT										41. Year 2016										42. Plate No. X63HYF										43. State NJ		68. Make Ford										69. Model Taurus										70. Color BK										71. Year 2016										72. Plate No. GKE2578										73. State NY		125																																																																		
01	44. VIN 3 N 1 A B 7 A P 5 G Y 3 2 0 8 5 6										45. Expires 05/19		74. VIN 1 F A H P 2 E 8 5 G G 1 3 4 0 0 3										75. Expires 09/19												126																																																																																																																																								
02	46. Vehicle Removed to: Brick Performance										47. Authority ☐ Owner ☒ Driver ☐ Police										48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - % ☐ Pending										49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No.										76. Vehicle Removed to: Sandys Service Center										77. Authority ☐ Owner ☒ Driver ☐ Police										78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - % ☐ Pending										79. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No.										126c																																																																																										
01	50. Carrier No. ☐ USDOT ☒ None										51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.										80. Carrier No. ☐ USDOT ☒ None										81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.																				126d																																																																																																																								
03	52. Motor Carrier or Government Entity										53. Motor Carrier or Government Entity										54. Motor Carrier or Government Entity										55. Motor Carrier or Government Entity										56. Motor Carrier or Government Entity										126e																																																																																																																								
	Number & Street										Number & Street										Number & Street										Number & Street										Number & Street										126f																																																																																																																								
	City										City										City										City										City										127a																																																																																																																								
	State										State										State										State										State										127b																																																																																																																								
	Zip										Zip										Zip										Zip										Zip										127c																																																																																																																								
	135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No																																																		127d																																																																																																																								
	Oper. 01										136. Charge 39:4-88B										137. Summons No. E19 000484										Oper. 01										138. Charge 39:4-97										139. Summons No. E19 000485										127e																																																																																																														
	Oper.										140. Charge										141. Summons No.										Oper.										142. Charge										143. Summons No.										128																																																																																																														
	83										84										85										86										87										88										89										90										91										92										93										94										95										Names & Addresses of Occupants If Deceased, Date & Time of Death										129																														
A	01										01										01										03										31										F										08										05										11										00										01										6505										DANIELLE MARIE DEMERS 2 CHERRYWOOD CIR BRICK TOWNSHIP NJ 08724										130																																								
B	02										01										01										04										55										F										05										08										02										11										04										-										6505										SHARON JILL CHESTER 56 JOSEPH BYRNE DR BRICK TOWNSHIP NJ 08724										131																														
C																																																																																																																																																							132																				
D																																																																																																																																																																											133

New Jersey Police Crash Investigation Report												Case Number 2019-00008921			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling North on Jack Martin Blvd. Vehicle #2 was traveling South on Jack Martin Blvd. Both vehicles collided head on, causing heavy front end damage to both.

Driver #1 advised she was traveling North when her front windshield completely fogged up. Driver #1 stated she reached over to turn the defrost on while still looking straight ahead, and then suddenly collided with Vehicle #2. Driver #1 was unsure if she crossed over into the other lane or if Vehicle #2 came into her lane, stating she could not see anything and that the collision happened so quickly. Driver #1 was also unsure if she was wearing her seat belt at the time of the collision. Driver #1 sustained contusions and abrasions on her right forearm and wrist, and also sustained abrasions and swelling to her right knee. She also complained of pain in her entire right arm and neck.

Driver #2 stated she was initially traveling South on Jack Martin Blvd and was about to make a left turn onto Frank Neri Drive when all of a sudden Vehicle #1 was directly in front of her coming head on. Driver #2 initially stated she may have been in the process of making the left turn when the collision occurred. She then stated that she believed she had not yet begun to negotiate the turn prior to the collision. Driver #2 stated she believes

146. Officer's Signature Michael V Bennett II	147. Badge # 279	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: — Case No: 2019-00008921

145 Crash Description

that she had her blinker on but was not certain. I asked if she knew whether Vehicle #1 crossed into her lane of travel but Driver #2 stated she did not know for sure. Driver #2 complained of chest pain, and was transported by her husband to Ocean Medical Center in his vehicle.

The location of Vehicle #1 was approximately thirty feet North of the intersection at Frank Neri Drive, and the driver side tire was resting on the centerline. Vehicle #2 was still in the Southbound lane, and was approximately sixty feet North of Vehicle #1. The majority of vehicle debris between both vehicles was in the Southbound lane just North of the location of Vehicle #1 and approximately fifty feet South of Vehicle #2. This would indicate that Vehicle #1 was traveling much faster than Vehicle #2, and as a result of the collision Vehicle #1 was pushed backwards significantly away from the point of impact. Based upon the location of the vehicles, and the location of the debris, it appeared that the head on collision occurred in the Southbound lane of travel approximately thirty feet North of Frank Neri Drive. If Driver #2 was already in the process of making the left turn, the collision and debris should have been much closer to or actually in the intersection of Jack Martin Blvd and Frank Neri Drive, not forty feet North of the intersection.

Based upon my observations, and statements made by both drivers, I find Driver #1 at fault for failing to maintain her lane of travel by crossing into the opposite lane and colliding with Vehicle #2. Upon serving Driver #1 with her traffic summonses at the hospital, she now stated for the first time that her vehicle must have hydroplaned because of the weather conditions. She also stated she did not believe she was at fault because when she turned the defrost on, the window cleared up enough for her to see black in front of her which she stated was Vehicle #2 who collided with her. While on scene previously, she was asked several times if she crossed into the other lane but she stated repeatedly that she did not know because she could not see anything.

BWC video available.

Michael V Bennett II


279

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2019-00008921

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Michael V Bennett II

279