

New Jersey Police Crash Investigation Report												Case Number 2019-00011155			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation revealed vehicle #1 crashed into the back left bumper of vehicle #2 with it's front left bumper causing damage while on the Olden Street ramp.

Driver of vehicle #1 stated she felt her vehicle going forward, and instead of hitting the brakes, she pressed the gas pedal causing the accident.

All involved parties were not injured and refused medical attention on scene.

Driver of vehicle #1 was issued a summons for 39:4-97 1506-E19-711

Driver of vehicle #2 was issued a summons for 39:3-4 1506-E19-710

This investigation was recorded on my body worn camera.

146. Officer's Signature Ryan A Valeri	147. Badge # 244	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:

Case No: 2019-00011155

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

NOT TO SCALE



Route 70

Olden Street



Ryan A Valeri

Officer's Signature

244

Badge Number