

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report


Case Number

2021-00019528

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was backing out of a parking spot in the parking lot of 455 Jack Martin Blvd. (AMI), while backing struck the right middle of Vehicle #2. Vehicle #2 was traveling North in the parking lot of 455 Jack Martin Blvd and was struck by Vehicle #1. No injuries were reported on scene, both vehicles were moved prior to my arrival.

Driver #1 stated she was backing out of her parking spot and did not see any vehicles near her. Driver #1 admitted fault and stated she never saw Vehicle #2 behind her.

Driver #2 stated he was traveling in the parking lot of 455 Jack Martin Blvd. attempting to exit the parking lot. when he felt Vehicle #1 back into the right side of his vehicle.

My investigation revealed that Driver #1 is at fault for the crash, due to backing unsafely and striking vehicle #2 causing the crash.

146. Officer's Signature

Edward McCaffery

147. Badge #

298

148. Reviewer

Jason M Matthews

Badge #

210



149. Case Status

☐ Pending ☒ Complete


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00019528

144 Crash Diagram (NOT TO SCALE)



455 Jack Martin Blvd (AMI)



Not To Scale

Edward McCaffery

Officer's Signature

298

Badge Number