

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2019-00004347					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 stopped in the right lane of Route 70 eastbound, just prior to Route 88. Vehicle 1 stopped directly behind Vehicle 2.

Driver 2 stated she was stopped in traffic waiting for the light to change when she was struck from behind by Vehicle 1. Driver 1 stated she was stopped behind Vehicle 2 when she saw Vehicle 2's brake lights go off. Believing Vehicle 2 was accelerating, Driver 1 began to accelerate and struck the rear of Vehicle 2.

Driver 1 was found to be at fault for inattention, by not realizing Vehicle 2 was not moving when she began to accelerate. Vehicle 2 is a Lexus IS300.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
John C Boronkas	165	Scott M Dierking	204	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2019-00004347

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



John C Boronkas

165