Page 1 of 3 ☐ Fatal

New Jersey Police Crash Investigation Report

☒ Reportable ☐ Non-Reportable ☐ Change Report

1. Case Number: 2019-00002597

2. Police Dept. of: Brick Police — Code: 01

3. Station/Precinct: —

10. Crash Occurred On: 425 JACK MARTIN BLVD (Road Name) — Dir: — — 11. Speed Limit: 45 — 12. Route No. — Suffix — 13. Milepost —

☐ At Intersection with ☐ Feet ☐ Miles — 14 — 15 — ☐N ☐E ☐S ☐W — 16 — of:

18. Speed Limit —

19. Ramp ☐To: ☐From: — 17. Cross Road Name/Route No. — ☐NB ☐SB ☐EB ☐WB

20 Route Name/Route No. — 21. Latitude — 22. Longitude —

4. Date of Crash (mm dd yy): 01 13 19 — 5. Day of Week: (S) M Tu W Th F Sa — 6. Time (use 2400 hrs.): 0717 — 7. Municipality Code: 1506 — 8. Total Killed: — — 9. Total Injured: — —

	Vehicle 1	Vehicle 2
23. Veh. #	01	—
24. Policy No.	PANJ-007517090	—
25. NJ Ins. Code	071	—
	☐ Parked ☐ Ped ☐ Pedalcylist ☐ Resp. to Emergency ☐ Hit & Run	☐ Parked ☐ Ped ☐ Pedalcylist ☐ Resp. to Emergency ☐ Hit & Run
26. / 56. Driver's First Name	JENSSE	—
Initial		—
Last Name	MARTINEZ	—
29. / 59. Sex	F	—
27. / 57. Number & Street	262 WESTWOOD AVENUE	—
28. / 58. City	LONG BRANCH	—
State	NJ	—
Zip	07740	—
30. / 60. Eyes	02	—
DL Class	D	—
Restrictions	— — — —	— — — —
Endorsements	— —	— —
31. / 61. State	NJ	—
32. / 62. Driver's License Number	M0691 39500 58892	—
33. / 63. DOB (mm dd yy)	08 06 89	—
34. / 64. Expires (mm yy)	04 21	—
35. / 65. Owner's First Name	☒ Same as Driver JENSSE MARTINEZ	☐ Same as Driver —
Initial		—
Last Name		—
36. / 66. Number & Street	262 WESTWOOD AVENUE	—
37. / 67. City	LONG BRANCH	—
State	NJ	—
Zip	07740	—
38. / 68. Make	Mazda	—
39. / 69. Model	MAZDA 3	—
40. / 70. Color	SL	—
41. / 71. Year	2016	—
42. / 72. Plate No.	U38JWP	—
43. / 73. State	NJ	—
44. / 74. VIN	JM1BM1U70G1333877	—
45. / 75. Expires	03/19	—
46. / 76. Vehicle Removed to:	Andrew's Auto Body	—
	☐ Driven ☒ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded	☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded
47. / 77. Authority	☐ Owner ☒ Driver ☐ Police	☐ Owner ☐ Driver ☐ Police
48. / 78. Alcohol Drug Test	Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.— % ☐ Pending	Given: ☐ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.— % ☐ Pending
49. / 79. Hazardous Material	☒ None ☐ On Board ☐ Spill — Hazard Class — Placard No.	☐ None ☐ On Board ☐ Spill — Hazard Class — Placard No.
50. / 80. Carrier No.	☐ USDOT — ☒ None ☐ MC/MX —	☐ USDOT — ☐ None ☐ MC/MX —
51. / 81. GVWR / GCWR *(trucks & buses only)*	☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.	☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.
52. / 82. Motor Carrier or Government Entity	—	—
Number & Street	—	—
City	—	—
State	—	—
Zip	—	—

135. Damage to Other Property ☐ Yes *(If Yes, describe)* ☒ No

Oper.	136. Charge	137. Summons No.	Oper.	138. Charge	139. Summons No.
—	—	—	—	—	—
Oper.	140. Charge	141. Summons No.	Oper.	142. Charge	143. Summons No.
—	—	—	—	—	—

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants *If Deceased, Date & Time of Death*
A	01	01	01	—	29	F	—	—	—	11	04	—	—	JENSSE MARTINEZ 262 WESTWOOD AVENUE LONG BRANCH NJ 07740
B														
C														
D														

New Jersey Police Crash Investigation Report	Case Number 2019-00002597	Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants *If Deceased, Date & Time of Death*
E														
F														
G														
H														
I														
J														

144. Crash Diagram

Show NORTH by Arrow (Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling South on Jack Martin Blvd. Vehicle 1 attempted to make a right turn into the parking lot 425 Jack Martin Blvd, thus striking the curbed divider. Vehicle 1 suffered front left wheel damage disabling the vehicle. Vehicle 1 was towed from the scene by Andrew's Auto Body.

The driver of vehicle 1 sustained no injuries.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
John C Rotondo	252	Joshua A Jenssen	225	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report Motor Vehicle Crash Diagram	Police Dept: Brick Police Code: 01 Station: — Case No: 2019-00002597

144 Crash Diagram (NOT TO SCALE)

Indicate North



John C Rotondo
Officer's Signature

252
Badge Number