

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2018-00074501					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling south in the parking lot of 1930 Rt 88 on an access road. Vehicle 1 then collided with a

curb dividing two parking areas.

The driver of vehicle 1 advised he was traveling on the access road of 1930 Rt 88 within the parking lot. Driver 1

further advised the sun glare was in his eyes when he collided with the curb.


146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Chase S Carter	280	Jason M Matthews	210	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2018-00074501

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



1930 RT 88



Chase S Carter

280