

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00071645			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling West on Rt 88, approaching the intersection of Rt 88 and Old Squan Road. Vehicle 1 was traveling directly behind vehicle 2.

The driver of Vehicle 2 stated traffic stopped quickly in front of her vehicle, and she slowed and drove on the shoulder to avoid a collision. Vehicle 1 was unable to stop, and the front of Vehicle 1 crashed into the rear of Vehicle 2, causing damage to both vehicle's.

The collision pushed vehicle 2 off of the shoulder and into utility pole VPS G12-16 SRP 18 4-40. The driver of vehicle 2 was transported to the hospital by EMS.

The driver of Vehicle 1 was issued a summons for 39:4-97.


146. Officer's Signature Brian Farnkopf	147. Badge # 230	148. Reviewer Austin E Kenny	Badge # 224	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00071645


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Final Rest

W Rt 88 E



Brian Farnkopf

Officer's Signature

230

Badge Number