

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00064226			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was parked head into a parking spot to the side of 457 Jack Martin Boulevard and an unknown vehicle struck vehicle 2. It is unknown what direction Vehicle 1 was traveling at the time of the collision.

I spoke to the driver of Vehicle 2 who stated she arrived and parked her vehicle at approximately 0955 hours and there were no vehicles parked around her. At approximately 1025 hours the driver of Vehicle 2 noticed the damage when she was approaching her vehicle to leave and contacted this agency. Driver of vehicle 2 was unable to provide any suspect vehicle information.

I observed a scuff mark on the passenger side rear door just above the door handle approximately one to one and a half feet in length. The damage appeared to be caused by another vehicle of similar size's side view mirror. There was no paint transfer and I was unable to locate any vehicle with consistent damage in the area. I spoke to management and there are no cameras on the property.

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer —	Badge # —	149. Case Status ☒ Pending ☐ Complete
---	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00064226

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael A DeFluri

Officer's Signature

270

Badge Number