

New Jersey Police Crash Investigation Report												Case Number 2018-00064742			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling west on Cedarbridge Ave approaching the red traffic signal located at the intersection with Jackson Ave. Vehicle #2 was heading north through the intersection from Jackson Ave with a green traffic signal. Vehicle #1 drove through a red traffic light as Vehicle #2 was crossing over Cedarbridge Ave to enter the Town Hall Shops and caused the crash.

The driver of Vehicle #1 stated in broken English that he was not paying attention to the traffic signal and did not see that his light was red as he entered into the intersection.

The driver of Vehicle #2 stated that she started into the intersection with a green light, trying to cross over to enter into the Town Hall Shops. She added that in doing so, Vehicle #1 went through the red light in front of her and caused the crash. She explained that after the crash, Vehicle #1 kept going and left the area.

Another driver, that wished to remain anonymous, stated that he witnessed the crash and followed Vehicle #1 to the Brick Mall. He explained that Vehicle #1 went through the red signal and caused the crash. He added that once it got to the Brick Mall, it parked to the rear (out of site) and the Hispanic driver walked away from it. He was said to have sat down in front of the Corner Post Diner where I later found him.

There were no injuries reported.

146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00064742

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Robert F Scelfo

Officer's Signature

189

Badge Number