

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00065637			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling south on Jack Martin Blvd. Vehicle 1 was traveling east through the parking lot of 495 Jack Martin Blvd and stopped for the stop sign to turn onto Jack Martin Blvd.

Vehicle 1 moved forward, and the front end of Vehicle 1 was on Jack Martin Blvd. The left front side of Vehicle 1 struck the right rear of Vehicle 2 as Vehicle 2 passed by.

The driver of Vehicle 1 possessed a valid Drivers Permit.

The driver of Vehicle 1 was issued a summons for obstructing the passage of other vehicles.

146. Officer's Signature Brian Farnkopf	147. Badge # 230	148. Reviewer Austin E Kenny	Badge # 224	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:



Case No: 2018-00065637

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Jack Martin Blvd



495 Jack Martin Blvd

Brian Farnkopf

Officer's Signature

230

Badge Number