

New Jersey Police Crash Investigation Report												Case Number 2018-00066634			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: The driver of V2 (vehicle 2) was in the left lane and was stopped at a red light 10 feet north from the intersection of Jack Martin Blvd / Route 70. The driver of V1 (vehicle 1) was traveling directly behind V2 and was approaching the red light. The accident occurred when the driver of V1 impacted the rear end of V2. On scene I did not observe any damage to the front end of V1 or the rear end of V2.

The driver of V2 stated she was stopped at the red light when she was impacted by V1. The driver of V1 stated he attempted to stop his vehicle but his brakes did not work as he collided into the rear of V2. The driver of V1 stated the wet road surface conditions attributed to his vehicle not stopping in time. Both drivers stated they were not injured and declined first aid attention. Both vehicles were removed from the roadway prior to my arrival.


146. Officer's Signature Kevin A Docherty	147. Badge # 275	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00066634

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Kevin A Docherty

Officer's Signature

275

Badge Number